



JW TRANSPORT

8200 Hampson Street
Suite 233
New Orleans, LA 70118

tel 504 861 7601
cel 504 261 8403
email jessew@jwtransport.com

NATIONAL CARGO BUREAU, INC.
Flat Rack Inspection Report

Port of Houston Reinspection

Location BARBOURS CUT TERMINAL Load Port HOUSTON, TX Discharge Port CURACAO
Vessel M/V "ZIM CANADA" Voyage N/A Booking No. GTN25850
Client JW TRANSPORT LLC Requested by JESSE WEISMAN Shipper:

Unit	
Unit Specific	
CSC Plate No.	
Next Inspection Date (or ACEP)	<u>IL-01</u>
Max Permissible Gross	<u>50,000</u> kg
Tare	<u>5,100</u> kg
Max Permissible Load	
Ends Positioned	<input type="checkbox"/> Up <input checked="" type="checkbox"/> Down <input type="checkbox"/> If Up, Locked <input type="checkbox"/> Yes <input type="checkbox"/> No
Measures	L <u>474</u> W <u>88</u> H <u>60</u> (in)
OOG Over height	<u>0</u> (in)
Over width (l)	<u>0</u> (r) <u>0</u> (in)
	<u>0</u> (r) <u>0</u> (in)
	[1inch=2.54 cm]

Actividades Logísticas

- ▶ Gestão de entregas
- ▶ Transportes, armazenagem e serviços aduaneiros
- ▶ Serviços ao cliente: um único ponto de contato

Cargo Description: STEEL PIPES; 49 PCS

WHERE CARGO COULD NOT BE ASSESSED, SURVEYOR UNABLE TO DETERMINE WHETHER THE USE OF EXTERNAL LASHINGS ONLY WOULD ADEQUATELY SECURE THE CARGO FOR THE INTENDED VOYAGE.


- ▶ Controle dos custos para o vendedor

- ▶ Faturamento de todos os serviços logísticos

Item	BS(kg)	MSL (kN)	#diags/eye	# crimps
<u>2" STEEL BAND (HALF LOOP)</u>		<u>46.0</u>	<u>2</u>	<u>4</u>

Weight distribution: Acceptable Not Acceptable
Blocked Yes No
Describe: 4" X 4" LUMBER

Securing Arrangements/F



Cargo is secured in acc

* Deficiencies Reported to N/A Date / Time 17-Feb-09 / 11:00

Signed

Surveyor's Name Printed CHRIS YOM

THIS CERTIFICATE IS NOT A FORM OF INSURANCE, OR GUARANTEE, AND IS ISSUED ON THE FOLLOWING TERMS AND CONDITIONS: This Certificate and performance of services by National Cargo Bureau ("NCB") shall in no way be deemed to be a representation, statement, or warranty of seaworthiness, quality or fitness for a particular use or service, of any vessel, container, cargo, structure, item of material, or equipment. NCB shall not be liable for, and the party to whom this Certificate is issued agrees to indemnify and hold NCB harmless from and against any and all claims, demands, actions for damages, including legal fees, to persons and/or property which may be brought against NCB incidental to, arising out of, or in connection with the services to be performed hereunder, except for those claims caused solely by the negligence of NCB. NCB shall be discharged from all liability for negligent performance or non-performance of any services rendered within one year after the date of issuance of this Certificate. NCB shall not be liable for any claim, or damage, arising from negligent performance of survey services. ANY IMPLIED OR EXPRESS WARRANTIES SHALL BE LIABLE FOR CHARGES TO THE PARTY TO WHOSE BENEFIT THIS CERTIFICATE MAY BE ISSUED.





JW TRANSPORT

8200 Hampson Street
Suite 233
New Orleans, LA 70118

tel 504 861 7601
cel 504 261 8403
email jessew@jwtransport.com

NATIONAL CARGO BUREAU, INC. Port of Houston Reinspection

Gestão Logística de Entregas

Location BARBOURS CUT TER... Flat Rack Inspection Report
Vessel M/V "ZIM CANADA" Voyage N/A Booking No. GTN25850
Client JW TRANSPORT LLC Requested by JESSE WEISMAN Shipper: _____

▶ Apoio dentro dos EUA e Canadá para as modalidades de vendas DDU/DDP

Unit Specifications 20 Ft 40 Ft
 CSC Plate Present Yes No Mass 25,486 kg
 Next Inspection Date (or A...)
 Max Permissible Gross H 60 (in)
 Tare (in)
 Max Permissible Load (in)
 Ends Positioned Up

Transportes, Armazenagem e Alfândega

▶ Portos: retiradas e devolução do containers

WHERE CARGO COULD NOT BE ASSESSED, SURVEYOR UNABLE TO DETERMINE WHETHER THE USE OF EXTERNAL LASHING OR SECURING MATERIALS IS NECESSARY FOR THE INTENDED VOYAGE.

▶ Container com excesso de peso

Securing Materials

Item	BS (kg)	MSL (kN)	#Slips/eye	# crimps
2" STEEL BAND (HALF LOOP)		46.0	2	4

Weight distribution:
 Acceptable Not Acceptable
 Blocked Yes No
 Describe:
 4" X 4" LUMBER

▶ Armazenagem: desova das mercadorias

▶ Disponibilidade de rede de armazéns para a distribuição

Securing Arrangements/Remarks

▶ 30 dias de armazenagem livre para um buffer

SECURED AT EACH SIDE WITH 9 X 2" STEEL BAND BY HALF LOOP LASHINGS; SECURING FORCE MEETS THE MINIMUM REQUIRED AMOUNT BASIS RULE OF THUMB CALCULATION/ANNEX 13: 9 X 4" = 411 kN > 250 kN. FOUR (4) CORNER FITTING HOLES CLEAR.

▶ Gestão das entregas ao destino final:

▶ Direto ao destino – on-dock até a porta do cliente

Cargo is secured in accordance with accepted principles of good seamanship. YES NO *

* Deficiencies Reported to N/A Date / Time 17-Feb-09 / 11:00

▶ Carregamento nos modais ferroviários e rodoviários

Plano de entregas e rastreabilidade
 Signed _____
 Shipper's Name Printed CHRIS YOM

THIS CERTIFICATE IS NOT A FORM OF INSURANCE, OR GUARANTEE, AND IS ISSUED ON THE FOLLOWING TERMS AND CONDITIONS: This Certificate and performance of services by National Cargo Bureau ("NCB") shall in no way be deemed to be a representation, statement, or warranty of seaworthiness, quality or fitness for a particular use or service, of any vessel, container, cargo, structure, item of material, or equipment. NCB shall not be liable for, and the party to whom this Certificate is issued agrees to indemnify and hold NCB harmless from and against any and all claims, demands, settlements, or damages, in connection with the services performance of any services rendered within one year after the date of issuance of this Certificate, OR FROM BREACH OF CONTRACT, OR FROM BREACH OF ANY IMPLIED OR EXPRESS WARRANTY, IN NO EVENT SHALL NCB BE LIABLE FOR CHARGES TO THE PARTY TO WHOSE BENEFIT THIS CERTIFICATE MAY BE ISSUED. Revised 05-05





JW TRANSPORT

8200 Hampson Street
Suite 233
New Orleans, LA 70118

tel 504 861 7601
cel 504 261 8403
email jessew@jwtransport.com

NATIONAL CARGO BUREAU, INC.
Flat Rack Inspection Report

Port of Houston Reinspection

Location BARBOURS CUT TERMINAL Load Port HOUSTON, TX Discharge Port CURACAO
Vessel M/V "ZIM CANAL" No. GTN25850
Client JW TRANSPORT Inspected by: _____



Unit ID		Mass	<u>25,486</u> kg,
Unit Specifications		Next Inspection Date (or ACEP)	<u>74</u> W <u>88</u> H <u>60</u> (in)
CSC Plate Present	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Max Permissible Gross	<u>50,000</u> kg
		OOG Over height	<u>0</u> (in)
		▶ Desde o momento que a mercadoria sai do Brasil até a entrega final (in)	
		Max Permissible Load	<u>44,900</u> kg
		Over length (f) <u>0</u> (r) <u>0</u> (in)	
Ends Positioned	<input type="checkbox"/> Up <input checked="" type="checkbox"/> Down If Up, Locked <input type="checkbox"/> Yes <input type="checkbox"/> No		[1inch=2.54 cm]

Serviços ao Cliente

- ▶ Um único ponto de contato
- ▶ Para o vendedor – relatórios de entregas em cada porto
- ▶ Para os clientes do vendedor – ETA, entregas especiais



Cargo Description ▶ **STEEL BANDS**
WHERE CARGO CONSISTED OF, OR INCLUDED, CASES, THE INTERIOR SECURING AND/OR CASE STRENGTH COULD NOT BE ASSESSED, SURVEYOR UNABLE TO DETERMINE WHETHER THE USE OF EXTERNAL LASHINGS MEETS THE CASED CARGO FOR THE INTENDED VOYAGE.

- ▶ Apoio pos-vendas

Item	BS(kg)	MSL (kN)	#drips/eye	# crimps
2" STEEL BAND (HALF LOOP)		<u>46.0</u>	<u>2</u>	<u>4</u>

Weight distribution:
 Acceptable Not Acceptable
 Blocked Yes No
 Describe:
4" X 4" LUMBER

- ▶ Controle dos custos logísticos para o vendedor

- ▶ Opções eficientes e de baixo custo proporcionando um nível do serviço superior

Securing Arrangements/Remarks
▶ Pesquisas constantes para melhoria da performance
SECURED AT EACH SIDE WITH 9 X 2" STEEL BAND BY HALF LOOP LASHINGS; SECURING FORCE MEETS THE MINIMUM REQUIRED AMOUNT BASIS RULE OF THUMB CALCULATION/ANNEX 13; 9 X 46 = 414 KN > 250 KN. FOUR (4) CORNER FITTING HOLES CLEAR.

Cargo is secured in accordance with accepted principles of good seamanship: YES NO *

* Deficiencies Reported to N/A Date / Time 17-Feb-09 / 11:00

Signed _____

Surveyor's Name Printed CHRIS YOM

THIS CERTIFICATE IS NOT A FORM OF INSURANCE, OR GUARANTEE, AND IS ISSUED ON THE FOLLOWING TERMS AND CONDITIONS: This Certificate and performance of services by National Cargo Bureau ("NCB") shall in no way be deemed to be a representation, statement, or warranty of seaworthiness, quality or fitness for a particular use or service, of any vessel, containers, cargo, structure, item of material, or equipment, or any and all claims, demands, actions for damages, or other legal proceedings, to be performed hereunder, except for those claims in connection with issuance of this Certificate, and performance of survey services. THE COMBINED LIABILITY OF NCB AND ITS SURVEYORS SHALL BE LIMITED TO THE AMOUNT OF THE FEE CHARGED TO THE PARTY TO WHOM THIS CERTIFICATE MAY BE ISSUED.





JW TRANSPORT

8200 Hampson Street
Suite 233
New Orleans, LA 70118

tel 504 861 7601
cel 504 261 8403
email jessew@jwtransport.com

NATIONAL CARGO BUREAU, INC.

Port of Houston Reinspection

Flat Rack Inspection Report

Conclusão

Location BARBOURS CUT TERMINAL Discharge Port CURACAO
Vessel M/V "ZIM CANADA" Voyage N/A Booking No. GTN25850
Client JW TRANSPORT LLC Requested by JESSE WEISMAN Shipper: _____

Unit ID ZCSH048956

Unit Specifications 20 Ft 40 Ft

CSC Plate Pro Utilizar transportes mais competitivos até o cliente final

Next Inspection Date (or ACEP) IL-01

Measures L 474 W 88 H 60 (in)

Max Permissible Gross 30,000 kg


Tare 5,100 kg

Max Permissible Load 44,900 kg

Ends Positioned Up Down


Offered to clients Oferecer aos clientes rastreabilidade - gestão de entregas

Use of warehouses in the port area Uso de armazéns na área retroportuaria para desova das mercadorias



Cargo Description: STEEL

WHERE CARGO CONSISTED OF, OR INC THE USE OF EXTERNAL LASHINGS ONLY



OR UNABLE TO DETERMINE WHETHER

Item	Quantity	Remarks
2" STEEL BAND (HALF LOOP)		

JW TRANSPORT
3700 ORLEANS AVENUE
NEW ORLEANS, LA 70119-4830
LOADING DIAGRAM 1
DATE: 09.13.2008

tribution:
ptable Not Acceptable
 Yes No

Securing Arrangements/Remarks

SECURED AT EACH SIDE WITH 9 X 2" STEEL BAND BY HALF LOOP LASHINGS; SECURING FORCE MEETS THE MINIMUM REQUIRED AMOUNT BASIS RULE OF THUMB CALCULATION/ANNEX 13; 9 X 46 = 414 KN > 250 KN. FOUR (4) CORNER FITTING HOLES CLEAR.

Cargo is secured in accordance with accepted principles of good seamanship: YES NO *

* Deficiencies Reported to N/A Date / Time 17-Feb-09 / 11:00

Signed _____

Surveyor's Name Printed CHRIS YOM

THIS CERTIFICATE IS NOT A FORM OF INSURANCE, OR GUARANTEE, AND IS ISSUED ON THE FOLLOWING TERMS AND CONDITIONS: This Certificate and performance of services by National Cargo Bureau ("NCB") shall in no way be deemed to be a representation, statement, or warranty of seaworthiness, quality or fitness for a particular use or service, of any vessel, container, cargo, structure, item of machinery or equipment, or any and all claims, demands, actions to be performed hereunder, except for in connection with issuance of this Certificate. NCB shall not be liable for any performance of survey services. THE ARISING FROM NEGLIGENCE OF ANY PARTY SHALL BE THE LIABILITY OF THAT PARTY. ANY IMPLIED OR EXPRESS WARRANTY SHALL BE THE LIABILITY OF THAT PARTY. NCB SHALL BE LIABLE FOR ANY CHARGES TO THE PARTY TO WHOM THIS CERTIFICATE MAY BE ISSUED.



unless from and against in connection with the services performance of any services provided within one year after CLAIM, OR DAMAGE OR FROM BREACH OF \$10,000. IN NO EVENT CUSTOMARY PORT THOSE BENEFIT THIS
RMB0405-05